BEAM #1 END #1

The pink line on the screwdriver is 1”.

BEAM #1



BUBBLING PAINT INDICATES TRAPPED MOISTURE. YOU CAN SEE THE 1” ROT/SHEET ROCK COVERAGE ALONG THE LEFT SIDE OF THE BEAM.

BEAM #2 END #1

1” MARK ON SCREWDRIVER

BEAM #2 END #1

ABOVE FRONT DOOR.
1” PINK MARK ON SCREWDRIVER.

BEAM #2 END #2

ABOVE SINGLE PANE WINDOW. BUBBLING PAINT INDICATES TRAPPED MOISTURE.

BEAM #2 END #2

ABOVE SINGLE PANE WINDOW

BEAM #2 END #2

1” MARK ON SCREWDRIVER

BEAM #3 END #1

1” MARK ON SCREWDRIVER

BEAM #3 END #2



1” MARK ON SCREWDRIVER

BEAM #4 END #1

CAN'T REACH

BEAM #4 END #2

CAN'T REACH